RESTRICTED

TECHNICAL SPECIFICATION - INTERFACE BOARD OF RADAR MONITOR CABINET FOR TRACKING RADAR TR-47C

Ser	Particulars	Description			
1.	Name of item	Interface Board			
2.	Quantity	01 (One)			
3.	Purpose	It is used for interfacing to IC and FCU-17 with RADAR.			
4.	Technical parameters	a.	Name of Main Equipment	Tracking RADAR TR-47C	
		b.	Part No	QW2.315.152/	
				QW7.820.7424	
		C.	10, 010, 110,	030403	
5.	Country of Origin	China			
6.	Country of Manufacturer	China			
7.	Year of Manufacturer	2022 or Later			
8.	Source of Supply	To be mentioned			
9.	Port of Shipment	Lebanon			
10.	Manufacture's Name &				
	Address				
11.	Supplier/Local Agent	To be mentioned			
12.	Certificate and Document of		OEM Certificate		
	Authentication	b Authorized Distributor Certificate			
		c. Authenticity and Genuine Certificate			
		d. Warranty Certificate			
			e. Classification Society/ Standard Certificate		
13.	Packing/Labeling	To be packed and labeled for international shipping			
14.	Warranty	At least 12 months from date of acceptance			
15.	Installation	- " Todas 12 months from date of acceptance			
16.	Test, Trail and Acceptance	-			
17.	Site visit (Focal Point)	-			
18.	Training	-	-		
19.	Accessories	-			
20.	Picture:				
		2		o minimum o	

M MAMUNUR RAHMAN 09.23
Commander BN
Electrical Officer
BNS SANGRAM

RESTRICTED

INCIDENT REPORT ON DEFECTIVE INTERFACE BOARD OF RADAR MONITOR CABINET FOR TRACKING RADAR TR-47C

RACKING RADAT	ct No. 241.193.15 dated 29 Sep 2015 between Banglade	sh Navy and China			
Reference: DGDP Contra	ternational Co. Ltd. (CSOC) BNS SANGRAM Date: 20 August 2023				
Chiphuilding & Offshore III	D-4 20 A 2022				
Ship's Name	BNS SANGRAM Date: 20 August 2023 n no Interface Board of Radar Monitor Cabinet for Trackin	g Radar TR-47C			
Subject Defect of one I	n no interface Board of Mass.				
	racking Radar TR-47C				
Name of Edail	ofacing of Tracking RADAK 1R-470 With FCU-17 laulty	due to fair wear and			
Description of Defect: III	the RADAR thoroughly with the guidance of OEM expert	and found Interface			
tear. Ships staff checked to	the RADAR thoroughly with the guidance of OLIM expert				
Board of TR-47C RADAR	Monitor Cabinet defective.				
Cause of Defect: Due to f	air wear and tear.	at 2023			
Location of Equipment:	PALIAR RUUIII				
Manufacturer:	Yangzhou Marine Electronic instrumentation Institute				
Manufacturer.	(723 Institute of CSIC) (YMEII)				
Supplier:	China Shipbuilding Heavy Industry Group No. 723				
Supplier.	Address: No. 26th, Yangzhou, Nan Jiang, Jiangsu				
	Province				
	Zip Code.: 225001				
	Tel: 0514-87807000				
	Fax: 0514-87232 229				
	e-mail: yz.723s@public.yz.js.cn				
	Web: http://www.yz723.com.cn/				
Part No:	QW2.315.152/ QW7.820.7424				
	030403				
Serial No/ Slot No:	Varranty Repair, Required Spares/Part/No/Quantity etc	c.)			
- I for Beer	d of Radar Monitor Cabinet for Tracking Radar TR-47C r	needs to be procured			
One in no Interface Board	J OI Radal Monitor Gabillet 10.				
at earliest.					
APPOINTMENT	NAME	SIGNATURE			
Commanding Officer	CAPT M AMIRUL ISLAM, (TAS), NPP, ncc, psc, BN	A A			
Electrical Officer	CDR M MAMUNUR RAHMAN, (L), psc, BN	MR 06.09.25			